


837 HEADER  
5800 0"

ERASE NOTE:  
OUTSWING HEAD FOR SURFACE CLOSERS




828 C.O.C. HEAD  
5800 0"

FOR USE WITH HINGES OR SURFACE CLOSERS  
FOR USE WITH HINGES OR SURFACE CLOSERS

841 O.G. VERT.  
5800 0"

ERASE NOTE:  
OUTSWING JAMB FOR OFFSET PIVOTS OR BUTT HINGE AS SHOWN, CONTINUOUS HINGE REQUIRES 1256


ERECTOR NOTE:  
APPLY CONTINUOUS BEAD OF SEALANT AROUND SHEAR BLOCK PRIOR TO SETTING MULLION IN PLACE.



843 O.G. VERT.  
5800 0"

ERASE NOTE:  
OUTSWING JAMB FOR OFFSET PIVOTS OR BUTT HINGE AS SHOWN, CONTINUOUS HINGE REQUIRES 1256


ERECTOR NOTE:  
APPLY CONTINUOUS BEAD OF SEALANT AROUND SHEAR BLOCK PRIOR TO SETTING MULLION IN PLACE.



ERASE NOTE:  
OUTSWING JAMB FOR OFFSET PIVOTS OR BUTT HINGE AS SHOWN, CONTINUOUS HINGE REQUIRES 1256

842 O.G. VERT.  
5800 0"


ERECTOR NOTE:  
APPLY CONTINUOUS BEAD OF SEALANT AROUND SHEAR BLOCK PRIOR TO SETTING MULLION IN PLACE.



838 O.G. JAMB  
5800 0"

ERASE NOTE:  
OUTSWING JAMB FOR OFFSET PIVOTS OR BUTT HINGE AS SHOWN, CONTINUOUS HINGE REQUIRES 1256

ERECTOR NOTE:  
APPLY CONTINUOUS BEAD OF SEALANT AROUND SHEAR BLOCK PRIOR TO SETTING MULLION IN PLACE.



ERASE NOTE:  
OUTSWING JAMB FOR OFFSET PIVOTS OR BUTT HINGE AS SHOWN, CONTINUOUS HINGE REQUIRES 1256

839 O.G. JAMB  
5800 0"

ERECTOR NOTE:  
APPLY CONTINUOUS BEAD OF SEALANT AROUND SHEAR BLOCK PRIOR TO SETTING MULLION IN PLACE.

