



430	JAMB
	325
	CASEMENT IN

ERECTOR NOTE:
THE HINGED JAMB FRAME SHALL BE INSTALLED PLUMB. ALL HINGES SHALL BE SECURELY BLOCKED AND ANCHORED TO THE CONDITION THROUGH THE HINGES OR AS CLOSE AS POSSIBLE TO THE HINGES.




432	JAMB
	325
	CASEMENT IN
	BUTT HINGES




630	MEETING RAIL
	325
	C.L. 1/2\"/>


130	HEAD
	325
	CASEMENT IN
	4-BAR ARMS



131	HEAD
	325
	CASEMENT IN
	BUTT HINGES



230	SILL
	325
	CASEMENT IN
	4-BAR ARMS



231	SILL
	325
	CASEMENT IN
	BUTT HINGES

